






4 Inch HD Radiator Cone (Part #175500) ▶

Larger Cone accessory for HD, Diesel, & Marine Engines. For use with the HECAT® ENGINE COOLING PULSATOR® (2 inch cone is not included - shown as "how to use").



For aircraft, truck, bus, and heavy equipment applications. For use with FAC-400, FAC-200, MARK IV or MARK II model flushers. Doubles the length of the standard equipment Flush & Return line sets. NOT for use with H1000 flusher (different quick couplers, call as needed).



For FAC-400, FAC-200, MARK IV or MARK II model flushers. NOTE: Clear bowl is not available separately.

■ Return Hose Assembly (Part #111733)

For use with FAC-400 or MARK IV model flusher. Includes T-Strainer, Clear bowl is not available separately.

3/8" T-Strainer Assembly for H1000 (Part #410001) ▶

NOTE: Clear bowl is not available separately.

◄ Sight Tube Repair Kit (Part #117655)

For H1000, FAC-400, or MARK IV model flusher. Includes 2 fittings & 2 lengths of Poly tubing.

Air filter Assembly (Part #118508) ▶

For use with FAC-200 and MARK II model flushers. Add on feature for older model flusher not equipped.

◄ Spin-On Filter (Part #400022)

For use with the H1000, FAC-400 and MARK IV model flushers. 2 filters are included in each case of SAFE-FLUSH[®]. Required (spec) filter for the H1000 Refrigerant flusher.

10 Inch Wheel Kit (Part #230016) ▶

10 inch dia. rib tread (qty 2), ½ inch hub bore, 1 ½ inch hub length. Cotter Pins and ½ inch Spacers (if needed) included.















